



RNAV (RNP) Z RWY 14
PALM BEACH INTL (PBI)


T For uncompensated Baro-VNAV systems, procedure NA below 6°C or above 54°C.

MISSED APPROACH: Climb to 2000 direct CUSIK and on track 204 to LANCH and hold.


CPDLC



VGSI and RNAV glidepath not coincident
(VGSI Angle 3.00/TCH 66).




See planview for multiple IF locations.



CATEGORY	A	B	C	D
RNP 0.30 DA		354-1	337 (400-1)	

AUTHORIZATION REQUIRED



PALM BEACH INTL (PBI)
RNAV (RNP) Z RWY 14