

23110


RNAV (GPS) RWY 10

LIMA ALLEN COUNTY (AOH)

T
A Rwy 10 helicopter visibility reduction below $\frac{3}{4}$ SM NA. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C.

MISSED APPROACH: Climb to 3000 direct DIZO and hold.

ASOS 128.725	COLUMBUS APP CON 121.825 323.15	UNICOM 122.7 (CTAF) 0
------------------------	---	---------------------------------



The diagram shows a horizontal line representing the runway axis. At the left end, there is a circle with a minus sign (-) and the number '01' below it. An arrow points from the text '096°' to this end. Along the line, there is a label '0.4% UP' with an arrow pointing to the right. Further right, there is a label '6000 X 150'. At the right end of the line, there is a circle with a plus sign (+) and the number '28' below it. Below the line, there is a star symbol with the number '1019' below it. To the right of the star, there is a small rectangular structure. At the bottom of the diagram, there are two labels: 'REIL Rwy 10 and 28' and 'HIRL Rwy 10-28'. To the right of these labels are two circular icons: the top one has a minus sign (-) and the bottom one has a plus sign (+).

LIMA ALLEN COUNTY (AOH)
RNAV (GPS) RWY 10

EC-2, 04 SEP 2025 to 02 OCT 2025