

VORTAC MSN 108.6 Chan 23	APP CRS 254°	Rwy Idg TDZE Apt Elev	4001 928 928
--	------------------------	-----------------------------	---


VOR RWY 28

MIDDLETON MUNI/MOREY FLD (C29)

T When local altimeter setting not received, use Dane County Rgnl/Truax Fld
A altimeter setting and increase all MDAs 40 feet and S-28 visibility Cat C $\frac{1}{8}$
SM, and Circling visibility Cat C $\frac{1}{4}$ SM. RADAR or DME required. Circling
NA to Rwy 15 and 19. Rwy 28 helicopter visibility reduction below 1 SM NA.
Straight-in Rwy 28 NA at night. Circling Rwy 28 NA at night.

MISSED APPROACH: Climb to 2000 then climbing right turn to 3500 on heading 020° and MSN R-282 to IMMES INT/9.2 DME and hold.

AWOS-3 118.675	MADISON APP CON★ 135.45 343.7	UNICOM 123.0 (CTAF) ①
--------------------------	---	---------------------------------



MIRMIL Rwy 10-28

	Knots	60	90	120	150	180
Min:Sec	8:24	5:36	4:12	3:22	2:48	