

APP CRS	Rwy Idg	8000
281°	TDZE	813
	Apt Elev	815

RNAV (RNP) Z RWY 28R

JOHN GLENN COLUMBUS INTL (CMH)

RNP AR APCH.

For uncompensated Baro-VNAV systems, procedure NA below -19°C or above 54°C. For map ALS, increase RNP 0.16 all Cats visibility to RVR 4500 and increase RNP 0.30 all Cats visibility to RVR 5500. Simultaneous approach authorized.

MALSR

MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 to APE VORTAC and hold.

D-ATIS	COLUMBUS APP CON	COLUMBUS TOWER	GND CON	CLNC DEL	CPDLC
124.6	125.95 371.975	132.7 257.8	121.9 348.6	126.3	

MISSED APCH FIX

4 NM

055°

235°

APPLETON APE

(IF) TEEZE

6000 210K

(RF REQD)

4900 101° (3.5)

DWYFE

1280

Δ1129

Δ1196

Δ1116

Δ1166

Δ1094

Δ1548

(IAF) FAVUS

5000 210K

3900 213° (3.5)

4000 281° (3.5)

BOLDS

(IF) WINAT

3300 251° (2)

3300 281° (2.1)

3300 311° (2)

SINPE

ORDIW

(IAF) YELU

3900 349° (3.6)

(IAF) WERUP

5000 210K

MSA RW28R 2.5 NM

3100

3500 151° (5.3)

GIMPS

2300 281° (3.2)

(FAF) WEEKZ

Δ1113

281° (4.5)

RW28R

5100 101° (3.2)

(IF) JESCE

6000 210K

(RF REQD)

HUSOR

1400 3000

APE

See planview for multiple IF locations.

WEEKZ

2300

281°

2300

GP 3.00°

TCH 50

4.5 NM

RW28R

CATEGORY	A	B	C	D
RNP 0.16 DA	1129/24	316 (400-½)		
RNP 0.30 DA	1185/35	372 (400-¾)		

AUTHORIZATION REQUIRED

ELEV 815

D

TDZE 813

TDZ/CL Rwy 10R-28L

HIRL Rwy 10R-28L and 10L-28R

EC-2, 02 OCT 2025 to 30 OCT 2025

EC-2, 02 OCT 2025 to 30 OCT 2025