

APP CRS

023°

Rwy Ldg

6607

TDZE

161

Apt Elev

168

RNAV (RNP) Y RWY 2

RICHMOND INTL (RIC)

RNP AR APCH.

▼

For uncompensated Baro-VNAV systems, procedure NA below -11°C (13°F) or above 54°C (130°F). Rwy 2 helicopter visibility reduction below ¾ SM NA. For inop ALS, increase RNP 0.11 all Cats visibility to 1 SM and RNP 0.3 all Cats visibility to 1¼ SM.

MALSR

MISSED APPROACH:

Climb to 2100 on track 023° to IMASE and hold.

ATIS	POTOMAC APP CON	RICHMOND TOWER	GND CON
119.15 263.025	126.4 282.375 (001°-185°) 126.75 307.2 (186°-360°)	121.1 257.8	121.9 348.6

See planview for multiple IF locations.

FISSR

1300

2100

IMASE

↑

tr 023°

1300

GP 3.00°

TCH 50

023°

RW02

3.4 NM

CATEGORY	A	B	C	D
RNP 0.11 DA		506-¾	345 (400-¾)	
RNP 0.30 DA		595-1	434 (500-1)	

AUTHORIZATION REQUIRED

ELEV 168

TDZE 161

RICHMOND, VIRGINIA

Org-B 19JUL18

37°30'N-77°19'W

RICHMOND INTL (RIC)

RNAV (RNP) Y RWY 2