



APP CRS	Rwy Ldg	9003
337°	TDZE	161
	Apt Elev	168


RNAV (RNP) Y RWY 34

RICHMOND INTL (RIC)

RNP AR APCH.	ALSIF-2	MISSED APPROACH: Climb to 2500 on track 337° to IFPIG and hold.
▼ For uncompensated Baro-VNAV systems, procedure NA below -11°C or above 54°C. For inop ALS, increase RNP 0.30 all Cats visibility to 1¼ SM.		

ATIS	POTOMAC APP CON	RICHMOND TOWER	GND CON
119.15 263.025	126.4 282.375 (001°-185°) 126.75 307.2 (186°-360°)	121.1 257.8	121.9 348.6



2500	IFPIG	See planview for multiple IF locations. VGSi and RNAV glidepath not coincident (VGSi Angle 3.00/TCH 79).		WOWSR
 fr 337°				1300
CATEGORY	A	B	C	D
RNP 0.11 DA		482/26	321 (400-½)	
RNP 0.30 DA		596/49	435 (500-1)	
AUTHORIZATION REQUIRED				