

ATIS
121.15
SANTA MARIA TOWER ★
118.3 (CTAF) **L** 239.25
GND CON
121.9
D

ATIS 121.15
 SANTA MARIA TOWER ★
 118.3 (CTAF) 239.25
 GND CON
 121.9
 D

ELEV 217
 0.5% UP
 123.3°
 HS 2
 ELEV 226
 HS 3
 203.9°
 8004 X 150
 5199 X 75
 0.3% UP
 023.3°
 ELEV 210
 0.6% DOWN
 303.3°
 FIELD ELEV 261
 HIRL Rwy 12-30
 Not for Part 121/Part 380 Air Carrier
 Use or Foreign Air Carrier
 Equivalent: RWY 02-20.
 CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
 READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

BCN
 ADMINISTRATION
 TWR
 TERMINAL
 FIRE STATION
 FBO
 CARGO RAMP
 JANUARY 2025
 ANNUAL RATE OF CHANGE
 0.1° W
 VAR 12.1° E
 34°54'N
 120°28'W
 120°27'W
 34°53'N

SANTA MARIA, CALIFORNIA
SANTA MARIA PUB/CAPT G ALLAN HANCOCK FLD (SMX)