

APP CRS 344°	Rwy Idg TDZE Apt Elev	9426 387 432
------------------------	-----------------------------	---

RNAV (RNP) Z RWY 34C
SEATTLE-TACOMA INTL (SEA)

RNP AR APCH.

T For uncompensated Baro-VNAV systems, procedure NA below -6°C or above 54°C. Simultaneous approach authorized except arrivals at SHIPZ. Use of FD or AP required during simultaneous operations.



MALSR



MISSED APPROACH: Climb to 5000 on track 344° to MGNUM and hold, continue climb-in-hold to 5000.

D-ATIS	SEATTLE APP CON	SEATTLE TOWER		GND CON	CLNC DEL	CPDLC
118.0	133.65 273.45	119.9 239.3	(Rwys 16L, 16C, 34C, 34R)	121.7	128.0	
		120.95 239.3	(Rwys 16R, 34L)			

MISSED APCH FIX



CATEGORY	A	B	C	D
RNP 0.30 DA	829/50 442 (400-1)			

AUTHORIZATION REQUIRED