

ARRIVAL ROUTE DESCRIPTION

From RDFLG on track 291° to HRDNG, then on track 287° to cross RNDRR at or above 6000 and at or below 220K.

LANDING RUNWAY 2L: From RNDRR on track 268° to cross KRIIS at or above 5000, then on track 220°. Expect assigned instrument approach procedure or RADAR vectors to final approach course.

LANDING RUNWAY 20R: From RNDRR on track 333° to cross ROAAD between 5000 and 6500 and at 210K, then on track 360°. Expect assigned instrument approach procedure or RADAR vectors to final approach course.

LOST COMMUNICATIONS

RUNWAY 2L: After KRIS, proceed on the RNAV (RNP) Z RWY 2L

approach. If unable, proceed to GLOWs for the ILS RWY 2L approach.

RUNWAY 20R: After ROAAD, proceed on the RNAV (RNP) Z RWY 20R approach. If unable, proceed to ZUREP at 5000 for the ILS RWY 20R approach.

FAIRBANKS APP CON
125.35 363.2
ATIS
124.4

RNAV 1 - GPS.

NOTE: Monitor ATIS for Rwy in use.

NOTE: Expect runway assignment from Fairbanks Approach upon initial contact.

NOTE: Chart not to scale.

