

RNAV (GPS) RWY 12

KING SALMON (AKN)(PAKN)

MISSED APPROACH:
Climb to 3000 direct
FELUM and on track
211° to JUTAN and
on track 272° to
OLLER and hold.

ELEV 73	D	TDZE 62
---------	----------	---------

The geological map shows a fault system with a main fault line labeled 'TWR' and a secondary fault line labeled 'Nw 36'. A well labeled 'A6' is located near the top left. The map includes a scale bar from 0 to 400 meters and a north arrow. The fault line is labeled with '81' and '4017' on one side, and '8901 X 130' on the other. The fault line is also labeled with '4017' and '1160' on the right side. The fault line is labeled with '4017' and '1160' on the right side. The fault line is labeled with '4017' and '1160' on the right side.

MIRL Rwy 18-36 **L**
HIRL Rwy 12-30 **L**

AK, 02 OCT 2025 to 27 NOV 2025