

TACAN RWY 14

TACAN EIL Chan 98	APCH CRS 142°	Rwy Idg 14,529 TDZE 537 Arpt Elev 548	[USAF]	EIELSON AFB (PAEI)
RADAR or DME required. RNAV or RADAR monitoring required for missed approach.			ALS-F-1	MISSED APPROACH: Climb to 4000 direct EIL TACAN, continue climbing right turn to intercept EIL TACAN R-249 to WAKOV and hold. Continue climb-in hold to 4000.
▼ *When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile, CAT CDE vis to 1¼ miles.			(A1) 	
ATIS ★ 119.9 273.5	ASOS 118.525	FAIRBANKS APP CON 127.1 251.1 (360° - 179°) 125.35 363.2 (180° - 359°)	TOWER ★ 127.2 352.05	GND CON 121.8 275.8 CLNC DEL 343.7

**Circling not authorized E of Rwy 14-32.

