


25275

ILS or LOC RWY 8R
GEORGE BUSH INTCNL/HOUSTON (IAH)

MALSR

MISSED APPROACH: Climb to 3000 on heading 087° and on DAS VORTAC R-242 to DAS VORTAC and hold.


D-ATIS 124.05	HOUSTON APP CON 120.05 379.1 E 124.35 316.15 W	HOUSTON TOWER 125.35 290.2	GND CON 118.575
-------------------------	--	--------------------------------------	---------------------------




SC-5, 02 OCT 2025 to 30 OCT 2025

SC-5. 02 OCT 2025 to 30 OCT 2025


ELEV 96	D	TDZE 95
---------	----------	---------




TDZ/CL Rwy's 8R, 8L, 15R, 26R, 26L,
27 and 33L
HRL qll Rwy's



MISSED APCH FIX



VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 72).



GEORGE BUSH INTCNTL/HOUSTON (IAH)

29°59'N-95°20'W

ILS or LOC RWY 8R