

ILS or LOC RWY 17L
DALLAS-FORT WORTH INTL (DFW)

MISSED APPROACH: Climb to 1020 then climbing left turn to 3000 on heading 151° and TTT VOR/DME R-127 to TACKE/TTT 26.5 DME and hold.

MISSED APCH FIX

TACKE
TTT [26.5]

113.1 TTT
Chan 78

R-127

ALTERNATE MISSED APCH FIX

TACKE
FUZ [32.7]

115.7 FUZ
Chan 104

R-120

RADAR REQUIRED

(IF)
RIVET
I-PPZ [19.6]
RADAR

DRAAK
I-PPZ [16.4]
RADAR

INWOD
I-PPZ [10.1]
RADAR

GBUSH
I-PPZ [7]
RADAR

IM

LOCALIZER 111.75
I-PPZ []
Chan 54(Y)

R-049

A 804

660 ±

MAVERICK
113.1 TTT []
Chan 78

R-127

MSA TTT 25 NM

090° → [] ← 270°

[] 2700

[] 3600

ELEV 607

D

TDZE 545

176°

181 188

17C

[illegible]