

MOUNT STERLING/MONTGOMERY COUNTY (IOB)

MISSED APPROACH:
Climb to 3000 direct
FELPO and hold.

CTAF
122.8