

PALM COAST, FLORIDA

AL-6440 (FAA)

25219

WAAS CH 66009 W11A	APP CRS 112°	Rwy Ldg 5500 TDZE 33 Apt Elev 33
--	------------------------	---

RNAV (GPS) RWY 11
FLAGLER EXEC (FIN)

RNP APCH.

T Circling NA to Rwy 18W and 36W.
A Rwy 11 helicopter visibility reduction below $\frac{3}{4}$ SM NA.


MISSED APPROACH: Climb to 2300 direct IBAYI and hold.

ATIS
128.325


DAYTONA APP CON
125.8 269.075

FLAGLER TOWER ★
118.95 (CTAF) **L**

GND CON
121.75

CLNC DE
121-75UNICOM
123.0

ELEV 33		TDZE 33
---------	--	---------



CATEGORY	A	B	C	D
LP MDA	420-1	387 (400-1)	420-1 $\frac{1}{8}$	387 (400-1 $\frac{1}{8}$)
LNAV MDA	540-1	507 (600-1)	540-1 $\frac{3}{8}$	507 (600-1 $\frac{3}{8}$)
CIRCLING	540-1	507 (600-1)	760-2 727 (800-2)	760-2 $\frac{1}{4}$ 727 (800-2 $\frac{1}{4}$)

REIL Rwys 6, 11 24, and 29 **L**
MIRL Rwys 6-24 and 11-29 **L**

PALM COAST, FLORIDA
Amdt 2A 15AUG19

29°28'N-81°12'W

FLAGLER EXEC (FIN)
RNAV (GPS) RWY 11