

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Idg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

⚠

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH:

Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF)
------------------------	---	-------------------------------

ELEV 2706	TDZE 2706	6000 HAYNI VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 25).				
		*LNAV only *1.7 NM to RWY 30 IBOXE 5 NM Holding Pattern 128° 308° 4300 5000 GP 3.00° TCH 40				
		CATEGORY	A	B	C	D
LPV		DA	2956-1		250 (300-1)	
LNAV/VNAV		DA	3233-1½		527 (600-1½)	
LNAV MDA		3260-1	554 (600-1)		3260-1½	554 (600-1½)
CIRCLING		3260-1	554 (600-1)		3260-1½	3460-2½ 554 (600-1½) 754 (800-2½)

HETTINGER, NORTH DAKOTA

Amclt 1 26MAY16

46°01'N-102°39'W

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

NC-1, 02 OCT 2025 to 30 OCT 2025