

ARRIVAL ROUTE DESCRIPTION	NOTE: RADAR required. NOTE: RNAV 1. NOTE: DME/DME/IRU or GPS required. NOTE: Turbojet aircraft only. NOTE: Expect to receive "descend via" clearance from Atlanta Center. NOTE: Select Rwy 10. NOTE: For use only when landing east. When landing west, file and expect the HOBTT ARRIVAL (RNAV).	D-ATIS ARR 119.65 ATLANTA APP CON 127.9 379.9
BEORN TRANSITION (BEORN.GNDLF2): COOUP TRANSITION (COOUP.GNDLF2): Assigned by ATC only. DRSDN TRANSITION (DRSDN.GNDLF2): ENNTT TRANSITION (ENNTT.GNDLF2): FRDDO TRANSITION (FRDDO.GNDLF2): GOLLM TRANSITION (GOLLM.GNDLF2): KHMVA TRANSITION (KHMVA.GNDLF2): Assigned by ATC only. ORRKK TRANSITION (ORRKK.GNDLF2): SHYRE TRANSITION (SHYRE.GNDLF2): STRDR TRANSITION (STRDR.GNDLF2): From GNDLF on track 059° to cross HALRR at or above 10000 and at 250K, then on track 059° to cross SHULR at 8000, then on track 036° to JNGLE, then on track 005° to QUBIT, then on track 005°. Expect RADAR vectors to find approach course.		
LOST COMMUNICATIONS: ASSIGNED RWY 10 or NOT ASSIGNED: Cross HALRR at or above 10000; cross SHULR at 8000; cross QUBIT at 5000; after QUBIT descend to 3000 and proceed direct DEWHY; proceed on the ILS or RNAV Rwy 10 approach. ASSIGNED RWY 9L: Cross HALRR at or above 10000; cross SHULR at 8000; cross QUBIT at 6000; after QUBIT proceed direct RYENN and proceed on the ILS or RNAV Rwy 9L approach. ASSIGNED RWY 9R: Cross HALRR at or above 10000; cross SHULR at 8000; cross QUBIT at 6000; after QUBIT proceed direct ANDY and proceed on the ILS or RNAV Rwy 9R approach. ASSIGNED RWY 8L: Cross HALRR at or above 10000; cross SHULR at 8000; cross QUBIT at 6000; after QUBIT proceed direct LARL and proceed on the ILS or RNAV Rwy 8L approach. ASSIGNED RWY 8R: Cross HALRR at or above 10000; cross SHULR at 8000; cross QUBIT at 6000; after QUBIT proceed direct GPEAT and proceed on the ILS or RNAV Rwy 8R approach.		