

25163

Rwy Ldg	8502
TDZE	1008
Apt Elev	1009

RNAV (GPS) RWY 36



JAMES M COX DAYTON INTL (DAY)

JAMES M COX DAYTON INTL (DAY)



For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C (-2°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Rwy 36 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

MISSED APPROACH: Climb to 3000 direct to KIRON and hold.

CLNC DEL
121,75

Procedure NA for arrival
at CINPA on V47 southwest
bound.




Diagram illustrating a flight path with headings and distances:

- Heading: 300°
- Distance: 6 NM
- Distance: 3.7 NM
- Distance: 1.4 NM
- Distance: 1.4 NM to RW36
- Distance: 1.4 NM only
- Distance: 1.4 NM

JAMES M COX DAYTON INTL (DAY)
RNAV (GPS) RWY 36