



ILS RWY 10 (SA CAT I)
LAKELAND LINDER INTL (LAL)

MISSED APPROACH: Climb to 1000 then climbing left turn to 2000 on heading 292° and on LAL VORTAC R-330 to PLUMY INT/PIE 33.4 DME and hold.

GND CON
121 4

TDZE 132

PLUMY



55

RA 152/14 150 DA 282

TDZ/CL Rwy 10
HIRL Rwy 5-23 and 10-28

SE-3, 30 OCT 2025 to 27 NOV 2025