

YIGO, GUAM I, GUAM

TACAN Z RWY 06L

TACAN UAM Chan 54	APCH CRS 065°	Rwy Idg 10,528 TDZE 539 Arpt Elev 617
-----------------------------	-------------------------	--

- (USAF)

ANDERSEN AFB (PGUA)

RADAR or DME required.

T * When ALS inop, increase CAT AB RVR to 55, vis to 1 mile, CAT CDE vis 1 3/8 miles.


A_2 

MISSED APPROACH: Climb to 3000, intercept UAM R-051 to FOVEM and hold.


ATIS 118.175 254.325	GUAM APP CON/DEP CON 119.8 269.0	TOWER 126.2 233.7	GND CON 121.7 275.8	CLNC DEL 126.725 256.7
-------------------------	-------------------------------------	----------------------	------------------------	---------------------------

CAUTION: Environmentally Sensitive Area. Flights along Andersen cliffline restricted to 1000' AGL or above

All touchdown zones have a 1.0% down slope.



EMERG SAFE ALT 100 NM 2900



YIGO, GUAM I, GUAM

13°35'N - 144°56'E

ANDERSEN AFB (PGUA)

Amdt 3 30NOV23
TERPS

TACAN Z RWY 06L

PAC, 02 OCT 2025 to 27 NOV 2025

PAC, 02 OCT 2025 to 27 NOV 2025