

ILS or LOC RWY 18L
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

MISSED APPROACH: Climb to 2500 then climbing left turn to 4000 on heading 160° and VUZ R-011 to FEWER INT/VUZ 39.4 DME and hold.

[illegible]

HUNTSVILLE INTL-CARL T JONES FLD (HSV)
W ILS or LOC RWY 18L