

LOC/DME I-ERP	APP CRS	Rwy Ldg	12000
111.55	263°	TDZE	5355
Chan 52(Y)		Apt Elev	5434

ILS or LOC RWY 25

DENVER INTL (DEN)

Simultaneous approach authorized with Rwy 26. For inoperative MALSR, increase S-LOC 25 Cat C and D visibility to RVR 5500.
**RVR 1800 authorized with use of FD or AP or HUD to DA.

MALSR

MISSED APPROACH: Climb to 10000 on heading 263° and on FQF VORTAC R-306 to HYGEN INT/FQF 37.9 DME and hold.

D-ATIS 125.6 379.9	DENVER APP CON 119.3 307.3 (N) 120.35 379.3 (S)	DENVER TOWER 128.75 273.55	GND CON 121.35 379.175 (W) 121.85 377.1 (E)
------------------------------	---	--------------------------------------	---

ELEV 5434	D	TDZE 5355
-----------	----------	-----------

DENVER, COLORADO
Amdt 3A 11DEC14

RADAR REQUIRED

DENVER INTL (DEN)

ILS or LOC RWY 25

39°52'N-104°40'W