

TACAN RWY 31R

VORTAC CBM 115.2 Chan 99	APCH CRS 302°	Rwy Idg 8016 TDZE 218 Arpt Elev 218
--	-------------------------	--

[USAF]

COLUMBUS AFB (KCBM)



T Missed approach requires use of RNAV or ATC RADAR monitoring.

MISSED APPROACH: Climbing right turn to WOLOV and hold as published. Maintain 3000.

ATIS ★	APP CON ★		TOWER ★	GND CON ★
115.2 273.5	N	126.075 239.25	126.65 379.925	121.9 275.8
	SE	134.55 350.3		
	SW	135.6 323.275		


Straight-in Rwy 31R at Night, operational VGSi required, remain on or above VGSi glidepath until threshold.

USAF Only: When VGSI inop, Straight-in Rwy 31R authorized at night with aircrew command approval. Visibility reduction by helicopters NA.




CALEDONIA
115.2 CBM 
Chan 99

EMERG SAFE ALT 100 NM 3700



CATEGORY	A	B	C	D	E
S-31R	680/55 462 (500-1)		680-1 $\frac{3}{8}$ 462 (500-1 $\frac{3}{8}$)		
CIRCLING	700-1 482 (500-1)	720-1 502 (600-1)	740-1 $\frac{1}{2}$ 522 (600-1 $\frac{1}{2}$)	880-2 662 (700-2)	1240-3 1022 (1100-3)



MIRL Rwy 13R-31L
HIRL Rwy 13C-31C, 13L-31R

COLUMBUS, MISS|SS|PP|

33° 39' N-88° 27' W

COLUMBUS AFB (KCBM)

Amdt 1 21APR22

TACAN RWY 31R

SC-4, 27 NOV 2025 to 25 DEC 2025

SC-4, 27 NOV 2025 to 25 DEC 2025