

25275

RNAV (RNP) Z RWY 28
LAKELAND UNDER INTL (LAL)

T

For uncompensated Baro-VNAV systems, procedure NA below -15°C or above 54°C.

MISSED APPROACH: Climb to 600 then climbing right turn to 2000 direct PLUMY and hold.

GND CON
121.4

4 NM

(IAF)
KATRE
3000 210K

3000
188°
(46)

MSA RW28 25 NM

2700

RW28

 (0.7)

1

▲

HC

1600

272°

(IF)

$$\overline{210K}$$

ELEV 142

D

TC

TDZE 142

600

200

PLU

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 71).

MAHZY

1

CATEGORY

A

D

RNP 0.30 DA

507/55 365 (400-1)

AUTHORIZATION REQUIRED

27°59'N-82°01'W

LAKELAND UNDER INTL (LAL)

RNAV (RNP) Z RWY 28