

ILS or LOC RWY 3
CASPER/NATRONA COUNTY INTL (CPR)

MALSR 	MISSED APPROACH: Climb to 7500 then left turn direct DDY VOR/DME and hold.
--	---

DME REQUIRED

IAF
MUDDY MOUNTAIN
116.2 DDY [---]
Chan 109

LOCALIZER 111.3
I-SYD [---]

MSA DDY 25 NM
7600
9500

090°
270°

(IAF) HIKOX DDY [27]

R-273

8300

DDY [27] Arc

GIPEC DDY [27]

R-222

7600

DDY [27] Arc

032° (2)

(IF) ISOYA DDY [29]

(LAGPE)

8200 to ISOYA
347° hdg (4.1)
and 032° (3.9)

IR-204

(IAF) CHOMP DDY [36]

212°

HATNO DDY [27]

032° (6.8)

MAMUE DDY [17.5]

SPIDE OM

R-193

JATEB DDY [29]

10300

DDY [29] Arc

R-137

(IAF) HEITY DDY [29]

6000

7000

8000

CASPER/NATRONA COUNTY INTL (CPR)
ILS or LOC RWY 3