

LOC/DME I-MFA 110.3 Chan 40	APP CRS 092°	Rwy Ldg 10506 TDZE 8 Apt Elev 9
---	------------------------	--

ILS or LOC RWY 8R

MIAMI INTL (MIA)

DME or RADAR required.	MALSR	MISSED APPROACH: Climb to 800 then climbing left turn to 3000 on heading 270° and on DHP VORTAC R-335 to BRBRA/DHP 11.5 DME and hold.
 For inop MALSR, increase S-ILS 8 all Cats visibility to 1½ mile. Simultaneous approach authorized with Rwy 9.		

D-ATIS 119.15	MIAMI APP CON 124.85 322.3	MIAMI TOWER 118.3 256.9	GND CON 121.8 (8L/8R/12/26L/26R) 348.6 127.5 (9/27/30)
-------------------------	--------------------------------------	-----------------------------------	---

