

ILS or LOC RWY 34
PORTSMOUTH INTL AT PEASE (PSM)

MALSR

MISSED APPROACH: Climb to 1500 then climbing left turn on heading 290° to 3000 and ENE VOR/DME R-242 to RAYMY INT/CON VOR/DME 22.5 DME/RADAR and hold.

Procedure NA for arrival on
ENE VOR/DME airway
radials 178 CW 271.

Procedure NA for arrival on
CON VOR/DME airway radials
061 CW 172.

Use of CON R-130 and ENE R-203 may be necessary to locate IDEED intersection.

1500	3000	ENE R-242	RAYMY △
------	------	--------------	------------

VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 80).

IDEED INT
PSM 12.3

One Minute Holding Pattern

