

25331


RNAV (RNP) Y RWY 10L
FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

MISSED APPROACH: Climb to 500, then climb to 4000 direct MARTS and hold, continue climb-in-hold to 4000.

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below 7°C or above 54°C.

GND CON

121.4



DZ

VGSI and RNAV glidepath not coincident
(VGSI Angle 3.00/TCH 66).

MARTS

See planview for multiple IF locations

PW101

GP 3.00°
TCH 49

330 (300-1/2)

391/35 384 (400- $\frac{5}{8}$)

AUTHORIZATION REQUIRED

HJRL Rwy 10L-28R and 10R-28L

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

26°04'N-80°09'W

RNAV (RNP) Y RWY 10L