

|         |          |      |
|---------|----------|------|
| APP CRS | Rwy Ldg  | 8394 |
| 276°    | TDZE     | 7    |
|         | Apt Elev | 65   |

RNAV (RNP) Z RWY 28R

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

RNP AR APCH - GPS. RADAR required.

Simultaneous approach authorized. For uncompensated Baro-VNAV systems, procedure NA below 7°C or above 54°C. For inop ALS, increase RNP 0.15 visibility to RVR 5500 and increase RNP 0.30 visibility to 1¾ SM.

MALSR

A5

MISSED APPROACH: Climb to 800 then climbing right turn to 4000 direct HUKUK and hold, continue climb-in-hold to 4000.

|                 |                                |                                      |                  |
|-----------------|--------------------------------|--------------------------------------|------------------|
| D-ATIS<br>135.0 | MIAMI APP CON<br>133.775 285.6 | FORT LAUDERDALE TOWER<br>119.3 257.8 | GND CON<br>121.4 |
|-----------------|--------------------------------|--------------------------------------|------------------|

MISSED APCH FIX  
4 NM  
307°  
127°  
HUKUK

Chart details: HUKUK (IF) 4000 210K, CUSRA, PRHIB (FAF) SNAPE, FUZZY (IF) 4000 210K, RWY 28R. Altitudes: 4000, 2500, 2000, 276°. Distances: 4.0, 3.2, 1.7, 6.3, 6.1 NM. Missed approach: 4000 290° (9.2) to HUKUK.

ELEV 65 TDZE 7

800 4000 HUKUK

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 69).

See planview for multiple IF locations.

276°

2000

GP 3.00° TCH 49

10L 28R

8000 X 150

10R 28L

8000 X 150

0.4% UP

1.0% DOWN

HIRL Rwy 10L-28R and 10R-28L

| CATEGORY    | A | B      | C            | D |
|-------------|---|--------|--------------|---|
| RNP 0.15 DA |   | 362/40 | 355 (300-¾)  |   |
| RNP 0.30 DA |   | 618-1⅓ | 611 (600-1⅓) |   |

AUTHORIZATION REQUIRED

FORT LAUDERDALE, FLORIDA

Amdt 2 12AUG21

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

26°04'N-80°09'W

RNAV (RNP) Z RWY 28R