

TACOMA, WASHINGTON

AL-5186 (FAA)

25331

WAAS CH 82608 W17A	APP CRS 167°	Rwy Ldg TDZE Apt Elev	5002 294 295
--	------------------------	-----------------------------	---

RNAV (GPS) RWY 17
TACOMA NARROWS (TIW)

RNP APCH.

- ▼** VDP NA with McChord Fld altimeter setting. For inoperative MALSR, increase LPV all Cats visibility to 1 ½ mile. Circling NA east of Rwy 17/35.
- ▲** Baro-VNAV NA when using McChord Fld altimeter setting. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C (5°F) or above 48°C (118°F). When local altimeter setting not received, use McChord Fld altimeter setting and increase all DA 25 feet, all MDA 40 feet, and increase LPV all Cats visibility ½ mile.

MALSR



MISSED APPROACH: Climb to 4000 direct WAPGI and right turn via 285° track to CARRO and hold, continue climb-in-hold to 4000.

ATIS 124.05	SEATTLE APP CON 120.1 290.9	TACOMA TOWER ★ 118.5 (CTAF) 0 253.5	GND CON 121.8	UNICOM 122.95
----------------	--------------------------------	--	------------------	------------------