

LOC RWY 5
NORTH CENTRAL STATE (SFZ)

MISSED APPROACH: Climb to 1000 then climbing left turn to 2500 on ORW VOR/DME R-057 to FOSTY INT/ ORW 23.5 DME and hold.

1148^Λ

ELEV 441 TDZE 429

5000 X 100

221 X 75

0.3% Up

047°

HIRL Rwy 5-23 1

MIRL Rwy 15-33 1

REIL Rwy 15, 23 and 33 0

FAF to MAP 6.4 NM

Knots	60	90	120	150	180
Min:Sec	6:24	4:16	3:12	2:34	2:08