

RNAV (GPS) RWY 22
ORANGE COUNTY (ORC)

MISSED APPROACH: Climb to 2000
direct KEDKY and left turn via track
116° to POPEY and hold

MSA RW22 25 NM

2400

1078 A

1163 A

628 A

262 A

298 A

RW22

410 A

KEDKY

254 A

(FAF) IBCED

(IF) WARES

(IAF) WLYMS

2000 130° (S)

2000 220° (E)

2000 310° (S)

1349 A

(IAF) SAHAJ

RADAR REQUIRED

ELEV 13 TDZE 13

MISSED APCH FIX

POPEY 116° 4 NM

ORANGE, TEXAS ORANGE COUNTY (ORG)
 Orig 22OCT09 30°04' N-93°48' W **RNAV (GPS) RWY 22**