

ILS or LOC RWY 9
BISHOP INTL (FNT)

MISSED APPROACH: Climb to 3000 on FNT VORTAC R-093 to HARRO/FNT VORTAC 10 DME/RADAR and hold.



CAUTION: Brightly lighted parking lot
4000' east of approach end of Rwy 27
can easily be confused for Rwy 27.

LOCALIZER 109.9
I-FNT

KROGR
FNT [6.5]

2600 to SELFY
275° (10.6)

(IF/IAF)
SELFY
FNT [10.6]
RADAR

HARRO
FNT [10]
RADAR

R-093

Procedure NA for arrival on FNT VORTAC
airway radials 234 CW 286.

MSA FNT 25 NM
[3100]

ELEV 782	D TDZE 771
----------	------------

ELEV 782 **D** TDZE 771

094° TWR 7201 X 150 7852 X 150 81 36 A5 Z

HIRL Rwys 9-27 and 18-36 **L**
 REIL Rwy 18 and 36 **L**

FAF to MAP 6 NM					
Knots	60	90	120	150	180
Min:Sec	6:00	4:00	3:00	2:24	2:00

EC-1, 22 JAN 2026 to 19 FEB 2026

EC-1, 22 JAN 2026 to 19 FEB 2026