


AIRPORT DIAGRAM

AL-330 (FAA)

PORTLAND INTL (PDX)
PORTLAND, OREGON

NW-1, 19 MAR 2026 to 16 APR 2026



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

AIRPORT DIAGRAM

PORTLAND, OREGON
PORTLAND INTL (PDX)

NW-1, 19 MAR 2026 to 16 APR 2026