




| | | |
|--|------------------------|---|
| WAAS CH 86606 W36B | APP CRS 005° | Rwy Ldg TDZE 595 Apt Elev 629 |
|--|------------------------|---|

RNAV (GPS) RWY 36R

HUNTSVILLE INTL-CARL T JONES FLD (HSV)

| | | |
|--|--------|---|
| RNP APCH - GPS. | MALSRL | MISSED APPROACH: Climb to 3000 direct BISBE and hold. |
| <p>ASR</p> <p>⚠ Circling NA for Cats C/D/E east of Rwy 18L-36R. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -9°C or above 54°C.</p> <p>Simultaneous approach authorized. LNAV procedure NA during simultaneous operations. Use of FD or AP required during simultaneous operations. For inop ALS increase LPV Cat E visibility to RVR 4000, LNAV/VNAV Cat E visibility to RVR 5000 and LNAV Cat E visibility to RVR 6000.</p> | | |

| | | | | |
|-----------------------|---|---|---------------------------------|-------------------------|
| ATIS 121.25 | HUNTSVILLE APP CON★ 125.6 354.1 | HUNTSVILLE TOWER★ 127.6 (CTAF) 0 350.35 | GND CON 121.9 269.525 | UNICOM 122.95 |
|-----------------------|---|---|---------------------------------|-------------------------|



SE-4, 19 MAR 2026 to 16 APR 2026

SE-4, 19 MAR 2026 to 16 APR 2026