

# OHARE NINE DEPARTURE



## DEPARTURE ROUTE DESCRIPTION

ALL AIRCRAFT: Expect RADAR vectors to first enroute navaid/fix.  
Expect clearance to requested altitude/flight level ten minutes after departure.

ALL AIRCRAFT: Cross 5.5 DME arc of GCO DME at or above 3000, cross  
8.5 DME arc of GCO DME at or above 4000, maintain 5000 or assigned altitude.  
If unable to comply advise ATC as soon as possible prior to departure.

EC-3, 16 APR 2026 to 14 MAY 2026

EC-3, 16 APR 2026 to 14 MAY 2026

# OHARE NINE DEPARTURE