

ARRIVAL ROUTE DESCRIPTION

ERICX TRANSITION (ERICX.TORGY4)

SSWAN TRANSITION (SSWAN.TORGY4)

UFFDA TRANSITION (UFFDA.TORGY4)

From TORGY on track 072° to cross OFSON at or above 11000 and at 280K, then on track 072° to cross HMBRG at or above 10000 and at or below 280K, then on track 073° to CONIA.

LANDING RUNWAYS 4, 17, 22, 30L: From CONIA on track 073° to cross JAEDN at or above 10000 and at 250K, then on track 073° to cross HDEEE at or above 9000, then on track 121° to cross MAUER at 8000 and at 210K, then on track 121° to cross LEDRZ at 8000 and at 210K, then on track 121°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 12L/R: From CONIA on track 042° to cross SPUKI at 7000 and at 230K, then on track 042° to cross KRUGG at 7000 and at 210K. Expect RNAV (RNP), RNAV (GPS), or ILS RWY 12R approach or RADAR vectors to RWY 12L/R final approach course.

LANDING RUNWAY 30R: From CONIA on track 073° to cross JAEDN at or above 10000 and at 250K, then on track 073° to cross HDEEE at or above 9000, then on track 059° to cross WILKN at 8000 and at 210K, then on track 122° to cross OSMOH at 8000 and at 210K, then on track 122°. Expect RADAR vectors to final approach course.

LANDING RUNWAY 35: From CONIA on track 073° to cross JAEDN at or above 10000 and at 250K, then on track 073° to cross HDEEE at or above 9000, then on track 121° to cross BRNVL at 8000 and at 210K, then on track 179° to cross LISEL at 8000 and at 210K, then on track 176°. Expect RADAR vectors to final approach course.

NC-1, 16 APR 2026 to 14 MAY 2026

NC-1, 16 APR 2026 to 14 MAY 2026