

ILS RWY 2L (CAT II & III)
FAIRBANKS INTL (FAI) (PAFA)

MISSED APPROACH: Climb to 900 then climbing right turn to 5000 on heading 170° and FAI VORTAC R-107 to KRNL/FAI 13 DME and hold, continue climb-in-hold to 5000.

 $\odot =$ [illegible]

ELEV 439	D	TDZE 439
----------	----------	----------

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED