

ARRIVAL ROUTE DESCRIPTION

BLYTHE TRANSITION (BLH ARJUNA4): From over BLH VORTAC on BLH R-089 and IWA R-256 to ARJUN INT. Thence, ...

PHOENIX SKY HARBOR INTL: Rwy 7L/R or 8: From over ARLIN, Expect vectors to final approach course; Rwy 25L/R or 26: From over ARLIN, on IWA R-256 to TUEEE. Expect vectors to final approach course prior to TUEEE.

SATELLITE AIRPORTS: Expect vectors after passing SCOLE or JUDTH.


LOST COMMUNICATIONS: After ARLIN, on IWA R-256 and PXR R-143 to PXR VORTAC.

NOTE: BLYTHE Transition for turbojet aircraft FL240 and above.

Turboprop aircraft plan BLYTHE ARRIVAL at or below FL230.

NOTE: MOHAK Transition for turbojet and turboprop aircraft.

NOTE: Turboprops landing KPHX expect vectors after passing SCOPE or JUDTH.



NOTE: RADAR required
NOTE: DME required
NOTE: Chart not to scale

NOTE: Chart not to scale.