




DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 19: Climb on JAC VOR/DME R-192 to KICNE/JAC 27 DME, cross KICNE at or above 15000, then on transition. Maintain ATC assigned altitude. Expect filed altitude 10 minutes after departure.

BIG PINEY TRANSITION (ALPIN5.BPI): From over KICNE on BPI R-305 to BPI VOR/DME.

IDAHO FALLS TRANSITION (ALPIN5.IDA): From over KICNE on IDA R-096 to IDA VOR/DME.