

ILS RWY 21L (SA CAT I & II)
DETROIT METRO WAYNE COUNTY (DTW)

MISSED APPROACH: Climb to 1100 then climbing left turn to 4000 on DXO R-122 to GAAGE/DXO 16 DME and hold, continue climb-in-hold to 4000.

CARLETON CRL
Chan 104

115.7
R-180

ALTERNATE
MISSED
APCH FIX


180°
360°
180°

(IAF) COUNT 5000
F-EJR 24.1
RADAR 5000


GIVVZ 5000
274° (2.6)
5000
226° (2.1)

TOFFY 6000
5200
306° (3.6)

(IAF) RYEDR 7000
210K



ELEV 645	D	TDZE 632
----------	----------	----------



**SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED**

HIRL all Rwys
REIL Rwys 3L, 9L, 9R and 21R
TDZL/RCLS Rwys 3R, 4L, 4R and 22R