

TACAN RWY 23

TACAN POB Chan 85	APCH CRS 232°	Rwy Idg TDZE 7500 200 Arprt Elev 225	[USAF]	POPE AAF (KPOB)
RADAR required				
* When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile; CAT CD vis to 1½ miles. ** Circling not authorized SE of Rwy 5-23. When circling to Rwy 5 at night, operational VGSI required, remain on or above VGSI glidepath until threshold.			ALSF-1 A1	MISSED APPROACH: Climbing right turn to 2000 on heading 285° and POB TACAN R-330 to AWGUS/POB 12 DME and hold.
ATIS 132.3 353.725		FAYETTEVILLE APP CON 125.175 285.575 (271° - 090°) 133.0 290.25 (091° - 270°)	TOWER 135.025 291.1	GND CON 124.55 275.8
HOLD 9000 2000 (IAF) AWGUS POB 12 ADEGE POB 12 Arc WALEP POB 5 COPIL POB 1.6 SIMMONS AAF POPE Chan 85 POB MSA POB 2.5 NM [3200] R-5311 A, B, C Missed Approach encroaches R-5311 CAUTION: Avoid R-5311 A, B, C located 2.5 DME West of field.				
EMERG SAFE ALT 100 NM 5300			ELEV 225	D TDZE 200
hdg 285° POB R-330 AWGUS POB 12 WALEP POB 5 GAYER POB 12 COPIP POB 1.6 POB TACAN 2.88° TCH 54 0.7 3.4 NM				
CATEGORY	A	B	C	D
S-23*	760-1	560 (600-1)	760-1½ 560 (600-1½)	
CIRCLING**	760-1	542 (600-1)	920-2 702 (800-2) 1060-2¾ 842 (900-2¾)	
HIRL Rwy 05-23 LIRL Rwy 05R-23L REIL Rwy 05 ASSAULT STRIP TWY				