

LOC/DME I-DLS	APP CRS	Rwy Ldg	4451
109.35	238°	TDZE	243
Chan 30(Y)		Apt Elev	247

LDA/DME RWY 25

COLUMBIA GORGE RGNL/THE DALLES MUNI(DLS)

NA

When local altimeter setting not received, procedure NA.
Glide slope provided by standard glide slope equipment.

MISSED APPROACH: Climb to 1600 then climbing left turn to 7000 on heading 120° and LTJ VOR/DME R-165 to JIREN/LTJ 15 DME and hold, continue climb-in-hold to 7000.

ASOS 135.175	SEATTLE CENTER 119.65 257.6	UNICOM 123.0 (CTAF) 1
------------------------	---------------------------------------	---------------------------------

LDA/GLIDE SLOPE

ELEV 247

TDZE 243

1600	7000	LTJ R-165	JIREN	Use I-DLS DME when on the localizer course.
↑	hdg 120°		△	
		LIREY I-DLS 8	CITAV I-DLS 10.5	VECCU I-DLS 13
		3800	4500	5300
		3800	238°	058°
		7.9 NM	2.5 NM	2.5 NM
CATEGORY	A	B	C	D
S-LDA/GS 25	1368-3	1125 (1200-3)		NA

REIL Rwy 31 1

MIRL Rwy 7-25 and 13-31 1

One Minute Holding Pattern

GS 4.20°

TCH 43

THE DALLES, OREGON

Amdt 1A 28APR16

COLUMBIA GORGE RGNL/THE DALLES MUNI(DLS)

45°37'N-121°10'W

LDA/DME RWY 25