

VUDOO TWO ARRIVAL (RNAV) Transition Routes

JOINT BASE ANDREWS (KADW)
CAMP SPRINGS, MARYLAND

POTOMAC APP CON
126.4 282.375
D-ATIS
133.675 251.05
TOWER
118.4 349.0

R-6611A & B

R-6613A

See following page
for arrival routes

VUDOO
9000

9000
*1500
045°
(10)

R-4006

TRUKK

9000
*1500
0310
0006
(9)

9000
*1500
078°
(16)

BEEVR
12000

6 NM

218°
(210K)

9000
*1500
038°
(9)

GOLOE
13000

10 NM

211°
(10)

11000
*2000
031°
(10)

HANKC

13000
*2000
022°
(9)

THHMP

NOTE: RADAR required.
NOTE: RNAV 1.
NOTE: DME/DME/IRU or GPS required.
NOTE: P56 area A/B 1.5 NM north of DCA,
avoid surface to 18000 MSL.

10 NM

190°
(230K)

VIIPR

13000
*1600
0110°
(26)

CIBAC

(CONTINUED ON FOLLOWING PAGE)

BEEVR TRANSITION (BEEVR.VUDOO2): (ATC assigned only).
CIBAC TRANSITION (CIBAC.VUDOO2)
THHMP TRANSITION (THHMP.VUDOO2)

NOTE: Chart not to scale.

VUDOO TWO ARRIVAL (RNAV) Transition Routes

CAMP SPRINGS, MARYLAND
JOINT BASE ANDREWS (KADW)