

ILS RWY 11 (CAT II & III)
WORCESTER RGNL (ORH)

MISSED APPROACH: Climb to 1800 then climbing right turn to 3100 on heading 230° and on GDM VOR/DME R-167 to LAWRN/GDM 23 DME and hold, continue climb-in-hold to 3100.

MSA GDM 25 NM

150° 4400

240° 3300

GARDNER
116.95 GDM
Chan 116(Y)

2900
187°
(16:5)

Procedure NA for arrival
on GDM VOR/DME airway
radials 179 CW 246.

ALTERNATE
MISSED
APCH FIX

115.6 MSL
Chan 103

121°

117.4 PUT
R-030
Chan 121

TROY INT
PUT 7.8

R-337

NE-1, 06 AUG 2026 to 03 SEP 2026

NE-1, 06 AUG 2026 to 03 SEP 2026

One Minute Holding Pattern

RILOC INT I-RSR 5.5

2800

6000 ← 289°

2800

109°

2800

109°

IM

1080

5.5 NM

1057'

CATEGORY	A	B	C	D
S-ILS 11		CAT II RA 119/12	100 DA 1080	
S-ILS 11		CAT III RVR 06		

CATEGORY II & III ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED