

VORTAC GLD 115.1 Chan 98	APP CRS 332°	Rwy Ldg 5499 TDZE 3654 Apt Elev 3657
--	------------------------	---

VOR RWY 30
RENNER FLD/GOODLAND MUNI (GLD)


▼ Inoperative table does not apply to S-30 Cat C/D. Circling NA south of Rwy 5 and 30. When local altimeter setting not received, use Burlington, CO altimeter setting and increase all MDA 160 feet; increase S-30 Cat C/D visibilities to 2 miles, Circling Cat C visibility to 2 miles and Circling Cat D visibility to 2½ miles. Circling Rwy 5, 23 NA at night. Circling NA to Rwy 5 and 30.

MALSR




MISSED APPROACH: Climbing right turn to 5600 in GLD VORTAC holding pattern.

ASOS 121.025	DENVER CENTER 132.7 226.675	UNICOM 122.8 (CTAF) 0
------------------------	---------------------------------------	---------------------------------



ELEV 3657		TDZE 3654
-----------	--	-----------

REIL Rwy 12 **L**

MIRL Rwy 5-23 and 12-30 L

