

DME required. RADAR required for procedure entry.



ALSF-2

MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on heading 270° and RQZ R-230 to JUVLO/RQZ 28.7 DME and hold.

Simultaneous approach authorized. DME from RQZ VORTAC.
DME use requires simultaneous reception of I-HSV and RQZ DME.

ASR

ATIS	HUNTSVILLE APP CON★	HUNTSVILLE TOWER★	GND CON	UNICOM
121.25	125.6 354.1	127.6 (CTAF) 0 350.35	121.9 269.525	122.95




CATEGORY	A	B	C	D
S-ILS 18R				

RA 105/12 100 DA 729

CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

ELEV 629

TDZE 629



TDZL/RCLS Rwy 18R and 36L

HIRL Rwy 18L-36R and 18R-36L