

TACAN RWY 23

TACAN POB Chan 85	APCH CRS 232°	Rwy Idg TDZE 7500 Arprt Elev 225	[USAF]	POPE AAF (KPOB)
-----------------------------	-------------------------	--	--------	-----------------

RADAR required

- * When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile; CAT CD vis to 1½ miles.
- ** Circling not authorized SE of Rwy 5-23. When circling to Rwy 5 at night, operational VGSI required, remain on or above VGSI glidepath until threshold.

ATIS 132.3 353.725	FAYETTEVILLE APP CON 125.175 285.575 (271° - 090°) 133.0 290.25 (091° - 270°)	TOWER 135.025 291.1	GND CON 124.55 275.8
------------------------------	--	-------------------------------	--------------------------------

Missed Approach encroaches R-5311
CAUTION: Avoid R-5311 A, B, C located 2.5 DME West of field.

POPE Chan 85 POB	MSA POB 2.5 NM [3200]
---------------------	--------------------------

ELEV 225	D	TDZE 200
-----------------	----------	-----------------

CATEGORY	A	B	C	D
S-23*	760-1	560 (600-1)	760-1½ 560 (600-1½)	
CIRCLING**	760-1	542 (600-1)	920-2 702 (800-2) 1060-2¾ 842 (900-2¾)	

HIRL Rwy 05-23
LRL Rwy 05R-23L
REIL Rwy 05

SE-2, 03 SEP 2026 to 01 OCT 2026