

26022

TACAN RWY 11L
FRESNO YOSEMITE INTL (FAT)

MISSED APPROACH: Climbing left turn to 2000 on CZQ
TACAN R-124 to SELMA/CZQ 18.6 DME and hold.

T
A Rwy 11L helicopter visibility reduction below $\frac{3}{4}$ SM NA.

EBTUW
LIN 57.7

2700
127°
(20.9)

R-307

(IF/IAF)
BEREN
CZQ 12.6

2700
127° (12.6)

086°

266°

131°

IAF
CLOVIS
Chan 76
CZQ 
(112.9)

131°

4.94

FAVOR
CZQ 4

MSA CZQ 25 NM

120°

7800

1900

300°

MISSED APCH FIX

CZQ
Chan 76 R-12
(112.9)

SELMA

131°

11L

11R

8530 x 150

8009 x 150

TWR

29L

29R

REIL Rwy 11L and 11R
 HIRL Rwy 11L-29R
 MIRL Rwy 11R-29L
 TDZL/RCLS Rwy 29R

CATEGORY	A	B	C	D	E
S-11L	760/55 424 (500-1)	760-1¼ 424 (500-1½)			
SIDESTEP 11R	760-1 427 (500-1)	760-1½ 427 (500-1½)		760-2 427 (500-2)	
CIRCLING	820-1 484 (500-1)	920-1½ 584 (600-1½)		920-2 584 (600-2)	1140-2¾ 804 (900-2¾)

FRESNO YOSEMITE INTL (FAT)

TACAN RWY 11L