

APP CRS
344°

Rwy Ldg
TDZE
387

Apt Elev
432

RNAV (RNP) Z RWY 34C

SEATTLE-TACOMA INTL (SEA)

RNP AR APCH.


▼

For uncompensated Baro-VNAV systems, procedure NA below -6°C or above 54°C. Simultaneous approach authorized except arrivals at SHIPZ. Use of FD or AP required during simultaneous operations.

MALSR

MISSED APPROACH: Climb to 5000 on track 344° to MGNUM and hold, continue climb-in-hold to 5000.

D-ATIS 118.0	SEATTLE APP CON 133.65 273.45	SEATTLE TOWER 119.9 239.3 (16L, 16C, 34C, 34R) 120.95 239.3 (16R, 34L)	GND CON 121.7
------------------------	---	--	-------------------------



ZINUB

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 73).

5000

MGNUM

2900

344°

2400

2400

See planview for multiple IF locations.

RW34C

GP 3.00°

TCH 56

1.6 NM

6.2 NM

CATEGORY	A	B	C	D
RNP 0.30 DA	829/50 442 (400-1)			
AUTHORIZATION REQUIRED				

